



# EQUIPOS SOLDADURA



---

**SAFETY SOLGAR, S.L., Telf. 638 57 37 37 - Fax. 93 588 14 61**  
**C/ Sierra Nevada, 5 y 7 - 08191 RUBI (Barcelona) SPAIN**

[www.safety-solgar.com](http://www.safety-solgar.com) - [Info@safety-solgar.com](mailto:Info@safety-solgar.com)



**78000018**

Con dos botellas (Ox-Ac, 5 l) soplete Gasweld, carro, válvulas de seguridad, 3 m de manguera, cruceta boquillas y manorreductor de Ox y Ac Gasweld

*Including 2 bottles (oxy-acetylene, 5 l), Gasweld torch, trolley, safety valves, 3 m hose, tip-holder, and Ox-Ac Gasweld regulator*

Para calefactores, instaladores, reparadores, obras, talleres de reparación de automóviles, auxiliares y de mantenimiento.

*For heating mechanics, tters, repairers, works, car, repair, ancillary and maintenance workshops*



**78000068**

Con botella Ox 5 l y botella butano 2,8 kg, soplete Gasweld, carro, 3 m de manguera, cruceta boquillas y manorreductor Gasweld Ox  
*Including 5 l oxygen and 2,8 kg butane bottles, Gasweld torch, trolley, 3 m hose and tip-holder, and Gasweld regulator Ox*

Para calefactores, instaladores, reparadores, obras, talleres de reparación de automóviles, auxiliares y de mantenimiento.

*For heating mechanics, tters, repairers, works, car, repair, ancillary and maintenance workshops.*



**78000190**

Con dos botellas (Ox-Ac, 10 l), soplete MINOR, carro universal, válvulas de seguridad, 3 m de manguera, boquillas soldar, dispositivo corte con boquillas y manorreductor. Ox y AC.

*Including two bottles (Ox-Ac, 10 l), MINOR torch, universal trolley, safety valves, 3 m hose welding tips, cutting device with tips and regulator. OX and AC.*

Para trabajos fuertes y continuados, tanto de soldadura como de corte.

*For strong and continuous work, both for welding and cutting.*

